

FIELD INSPECTION REPORT

Date of Inspection :	15.12.2020	District :	Munger
Division :	Kharagpur - Tarapur	Length (Km) :	2.6 Km.
Name of the Road :	Belbihuna to Kaliyanpur Road.		
Scheme/Programme :	MAINTENANCE / NMP 2018		
Package No. :		Road Id No. :	SL No. : - 36.
Status of the Project :	Ongoing/Completed/Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	✓S/U	
b)	Condition of Surfacing	✓S/U	
c)	Riding Quality	✓S/U	
d)	Road Camber	✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No	
g)	Compaction of flank/slope & raincuts if any	✓Yes/No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	} NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No	
4	Compliance History		
a)	Status of ATR's & any others	No	

Overall Rating :

Satisfactory (S) ✓	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME : Suresh Kumar
DESIGNATION : A.E

S. Kumar
15.12.2020
(Signature)

FIELD INSPECTION REPORT

Date of Inspection :	05.12.2020	District :	Munger
Division :	Kharagpur - Tarapur	Length (Km) :	1.5 Km
Name of the Road :	Gazipur to Khanpur path		
Scheme/Programme :	MAINTENANCE ✓ old NR(3054)		
Package No. :		Road Id No. :	
Status of the Project :	Ongoing/Completed/Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	✓S/U	
b)	Condition of Surfacing	✓S/U	
c)	Riding Quality	✓S/U	
d)	Road Camber	✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No	
g)	Compaction of flank/slope & raincuts if any	✓Yes/No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No	
4	Compliance History		
a)	Status of ATR's & any others	No	

Overall Rating :

Satisfactory (S) ✓	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME : Suresh Kumar
DESIGNATION : A.E

S. Kumar
05.12.2020
(Signature)

FIELD INSPECTION REPORT

Date of Inspection :		04.12.2020		District :		MUNGER.	
Division :		KHARAGPUR-TARAPUR		Length (Km) :		5.620 K.M.	
Name of the Road :		Kharagpur - Jamui Raipura Se Sichaikahar hote hue Daripur path.					
Scheme/Programme :		MAINTENANCE / OR MR(3054)					
Package No. :				Road Id No. :		Project ID- 20803808045	
Status of the Project :		Ongoing/Completed/Under Maintenance ☒					
Work is a case of :		New Connectivity/Up gradation/Maintenance ☒					
Sl. No.	Parameters to be checked					Remarks	
1	Pavement						
a)	Road Junction condition					☒ S/U	
b)	Condition of Surfacing					☒ S/U	
c)	Riding Quality					☒ S/U	
d)	Road Camber					☒ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.					☒ Yes/No	
f)	Contraction Joints provided or not (CC Pavement)					☒ Yes/No	
g)	Compaction of flank/slope & raincuts if any					☒ Yes/No	
2	Cross Drainage						
a)	Condition of head walls in Hume pipe culverts including its painting					S/SRI/U	N.A.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts					S/SRI/U	
c)	Condition of railings/slab/approach for Bridges					S/SRI/U	
3	Road Furniture						
a)	Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained					☒ Yes/No	
4	Compliance History						
a)	Status of ATR's & any others					NO.	

Overall Rating :

Satisfactory (S) ☒	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME : SUKESH KUMAR.
DESIGNATION : A.E.

S. K. Kumar
04.12.2020
(Signature)

FIELD INSPECTION REPORT

Date of Inspection :	04.12.2020	District :	MUNGER.
Division :	KHARAGPUR- TARAPUR.	Length (Km) :	2.250 KM.
Name of the Road :	Kharagpur - Muzaffargarh PMGSY Path me Rajganj se Ghoshpur Rote hue Teghra tak Path.		
Scheme/Programme :	MAINTENANCE -		
Package No. :		Road Id No. :	Project ID - 20803800844
Status of the Project :	Ongoing/Completed/Under Maintenance ☒		
Work is a case of :	New Connectivity/Up gradation/Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	☒ S/U	
b)	Condition of Surfacing	☒ S/U	
c)	Riding Quality	☒ S/U	
d)	Road Camber	☒ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	☒ Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	☒ Yes/No	
g)	Compaction of flank/slope & raincuts if any	☒ Yes/No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	N.A.
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained	☒ Yes/No	
4	Compliance History		
a)	Status of ATR's & any others	NO.	

Overall Rating :

Satisfactory (S) ☒	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME : SUKESH KUMAR
DESIGNATION : A.E.

S.K.
04.12.2020
(Signature)

FIELD INSPECTION REPORT

Date of Inspection :	04.12.2020	District :	MUNGER.
Division :	KHARAGPUR- TARAPUR.	Length (Km) :	4.100 Km.
Name of the Road :	Repair of road from Bahama more to khagraun.		
Scheme/Programme :	MAINTENANCE		
Package No. :		Road Id No. :	Project ID- 208038061
Status of the Project :	Ongoing/Completed/Under Maintenance		☒
Work is a case of :	New Connectivity/Up gradation/Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	☒ S/U	
b)	Condition of Surfacing	☒ S/U	
c)	Riding Quality	☒ S/U	
d)	Road Camber	☒ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	☒ Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	☒ Yes/No	
g)	Compaction of flank/slope & raincuts if any	☒ Yes/No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	} NA.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained	☒ Yes/No	
4	Compliance History		
a)	Status of ATR's & any others	No.	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME : SURESH KUMAR.
DESIGNATION : A-E.

S. Kumar
04.12.2020
(Signature)