

FIELD INSPECTION REPORT

Date of Inspection :	05.12.2020	District :	MUNGER.
Division :	Khazagpur - Tarapur.	Length (Km) :	4.600 Km
Name of the Road :	Khazagpur - Tarapur PWD Road to Pauchri		
Scheme/Programme :	MAINTENANCE NEW- MR-3054.		
Package No. :		Road Id No. :	SL No 32
Status of the Project :	Ongoing/Completed/Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	✓S/U	
b)	Condition of Surfacing	✓S/U	
c)	Riding Quality	✓S/U	
d)	Road Camber	✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No	
g)	Compaction of flank/slope & raincuts if any	✓Yes/No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	PROGRESS
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained	Yes/No Large Board only	WORK IN
4	Compliance History		
a)	Status of ATR's & any others	No.	

Overall Rating :

Satisfactory (S)	✓
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME : SUKESH KUMAR.
DESIGNATION : A.E.

S. K. K.
05.12.2020
(Signature)

FIELD INSPECTION REPORT

Date of Inspection :	04.12.2020	District :	MUNGER
Division :	KHARAGPUR - TARA PUR	Length (Km) :	10.200 K.M.
Name of the Road :	To2 Khazagpur Kulahara more to Bhumbi Pul Shaktan Gram via Rajganj, Ratni and Ratai the Road.		
Scheme/Programme :	MAINTENANCE ✓ MR- 3054 (old)		
Package No. :		Road Id No. :	Project 1D- 20803808037
Status of the Project :	Ongoing/Completed/Under Maintenance ✓		
Work is a case of :	New Connectivity/Up gradation/Maintenance ✓		
Sl. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	✓ S/U	
b)	Condition of Surfacing	✓ S/U	
c)	Riding Quality	✓ S/U	
d)	Road Camber	✓ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No	
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	N.A.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No	
4	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S) ✓	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME : SUKESH KUMAR.
DESIGNATION : A.E.

S. K. Kumar
04.12.2020
(Signature)

FIELD INSPECTION REPORT

Date of Inspection :	15.12.2020	District :	Munger
Division :	Kharagpur - Tarapur	Length (Km) :	2.6 Km.
Name of the Road :	Belbihuna to Kaliyanpur Road.		
Scheme/Programme :	MAINTENANCE / NMP 2018		
Package No. :		Road Id No. :	SL No. : - 36.
Status of the Project :	Ongoing/Completed/Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	✓S/U	
b)	Condition of Surfacing	✓S/U	
c)	Riding Quality	✓S/U	
d)	Road Camber	✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No	
g)	Compaction of flank/slope & raincuts if any	✓Yes/No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	} NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No	
4	Compliance History		
a)	Status of ATR's & any others	No	

Overall Rating :

Satisfactory (S) ✓	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME : Suresh Kumar
DESIGNATION : A.E

S. Kumar
15.12.2020
(Signature)

FIELD INSPECTION REPORT

Date of Inspection :	05.12.2020	District :	Munger
Division :	Kharagpur - Tarapur	Length (Km) :	1.5 Km
Name of the Road :	Gazipur to Khanpur path		
Scheme/Programme :	MAINTENANCE ✓ old NR(3054)		
Package No. :		Road Id No. :	
Status of the Project :	Ongoing/Completed/Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	✓S/U	
b)	Condition of Surfacing	✓S/U	
c)	Riding Quality	✓S/U	
d)	Road Camber	✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No	
g)	Compaction of flank/slope & raincuts if any	✓Yes/No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No	
4	Compliance History		
a)	Status of ATR's & any others	No	

Overall Rating :

Satisfactory (S) ✓	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME : Suresh Kumar
DESIGNATION : A.E

S. Kumar
05.12.2020
(Signature)

FIELD INSPECTION REPORT

Date of Inspection :	04.12.2020	District :	MUNGER
Division :	KHARAGPUR-TARAPUR	Length (Km) :	5.620 K.M.
Name of the Road :	Kharagpur - Jamui Raipura Se Sichaikahar hote hue Daripur path		
Scheme/Programme :	MAINTENANCE / O.D. MR(3054)		
Package No. :		Road Id No. :	Project ID- 20803808045
Status of the Project :	Ongoing/Completed/Under Maintenance <input checked="" type="checkbox"/>		
Work is a case of :	New Connectivity/Up gradation/Maintenance <input checked="" type="checkbox"/>		
Sl. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	<input checked="" type="checkbox"/> S/U	
b)	Condition of Surfacing	<input checked="" type="checkbox"/> S/U	
c)	Riding Quality	<input checked="" type="checkbox"/> S/U	
d)	Road Camber	<input checked="" type="checkbox"/> S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	<input checked="" type="checkbox"/> Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	<input checked="" type="checkbox"/> Yes/No	
g)	Compaction of flank/slope & raincuts if any	<input checked="" type="checkbox"/> Yes/No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	N.A.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained	<input checked="" type="checkbox"/> Yes/No	
4	Compliance History		
a)	Status of ATR's & any others	NO.	

Overall Rating :

Satisfactory (S) <input checked="" type="checkbox"/>	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME : SUKESH KUMAR.
DESIGNATION : A.E.

S. K. Kumar
04.12.2020
(Signature)

FIELD INSPECTION REPORT

Date of Inspection :	04.12.2020	District :	MUNGER.
Division :	KHARAGPUR- TARAPUR.	Length (Km) :	2.250 KM.
Name of the Road :	Kharagpur - Muzaffargarh PMGSY path me Rajgarh se Ghoshpur Rote hue Teghra tak path.		
Scheme/Programme :	MAINTENANCE -		
Package No. :		Road Id No. :	Project ID - 20803800844
Status of the Project :	Ongoing/Completed/Under Maintenance <input checked="" type="checkbox"/>		
Work is a case of :	New Connectivity/Up gradation/Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	<input checked="" type="checkbox"/> S/U	
b)	Condition of Surfacing	<input checked="" type="checkbox"/> S/U	
c)	Riding Quality	<input checked="" type="checkbox"/> S/U	
d)	Road Camber	<input checked="" type="checkbox"/> S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	<input checked="" type="checkbox"/> Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	<input checked="" type="checkbox"/> Yes/No	
g)	Compaction of flank/slope & raincuts if any	<input checked="" type="checkbox"/> Yes/No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	N.A.
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained	<input checked="" type="checkbox"/> Yes/No	
4	Compliance History		
a)	Status of ATR's & any others	NO.	

Overall Rating :

Satisfactory (S) <input checked="" type="checkbox"/>	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME : SUKESH KUMAR
DESIGNATION : A.E.

S.K.
04.12.2020
(Signature)

FIELD INSPECTION REPORT

Date of Inspection :	04.12.2020	District :	MUNGER.
Division :	KHARAGPUR- TARAPUR.	Length (Km) :	4.100 Km.
Name of the Road :	Repair of road from Bahama more to khagraun.		
Scheme/Programme :	MAINTENANCE		
Package No. :		Road Id No. :	Project ID- 208038061
Status of the Project :	Ongoing/Completed/Under Maintenance		<input checked="" type="checkbox"/>
Work is a case of :	New Connectivity/Up gradation/Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	<input checked="" type="checkbox"/> S/U	
b)	Condition of Surfacing	<input checked="" type="checkbox"/> S/U	
c)	Riding Quality	<input checked="" type="checkbox"/> S/U	
d)	Road Camber	<input checked="" type="checkbox"/> S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	<input checked="" type="checkbox"/> Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	<input checked="" type="checkbox"/> Yes/No	
g)	Compaction of flank/slope & raincuts if any	<input checked="" type="checkbox"/> Yes/No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	} NA.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained	<input checked="" type="checkbox"/> Yes/No	
4	Compliance History		
a)	Status of ATR's & any others	No.	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME : SURESH KUMAR.
DESIGNATION : A-E.

S. Kumar
04.12.2020
(Signature)