

# FIELD INSPECTION REPORT

Date of Inspection :		04.12.2020.		District :		MUNGER.	
Division :		Khazegpur - Tazapur		Length (Km) :		1.700 K.M.	
Name of the Road :		PWD Sangamur main road to Jnardhandi via Ropa more					
Scheme/Programme :		MAINTENANCE MR- 3054 (NEW)					
Package No. :				Road Id No. :		SL. No. 9.	
Status of the Project :		<input checked="" type="checkbox"/> Ongoing/Completed/Under Maintenance					
Work is a case of :		New Connectivity/Up gradation/Maintenance					
Sl. No.	Parameters to be checked					Remarks	
1	Pavement						
a)	Road Junction condition					S/U	PROGRESS
b)	Condition of Surfacing					S/U	
c)	Riding Quality					S/U	
d)	Road Camber					S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.					Yes/No	
f)	Contraction Joints provided or not (CC Pavement)					Yes/No	
g)	Compaction of flank/slope & raincuts if any					Yes/No	
2	Cross Drainage						
a)	Condition of head walls in Hume pipe culverts including its painting					S/SRI/U	IN
b)	Condition of Abutment & Wing walls, Slab in RCC culverts					S/SRI/U	
c)	Condition of railings/slab/approach for Bridges					S/SRI/U	
3	Road Furniture						
a)	Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained					<input checked="" type="checkbox"/> Yes/No	WORK
4	Compliance History						
a)	Status of ATR's & any others					No	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: RAM DARSHAN RAM.  
DESIGNATION: J. E.

(Signature)