FIELD INSPECTION REPORT

Date of Inspection :		04.12.2020.	District :	MUNGER.		
Division: Khazage		248- Tabe bus	Length (Km):	3.250 K.M.		
Name of the Road :		Construction of road from Kharagpro-Gangla main road to Kathana Sc tola wa chhitaki manjhain Road.				
Scheme/Programme :		MAINTENANCE NEW- MR-3054.				
Package No. :			Road Id No. :	SLINO	26	
Status of the Project :		Ongoing/Completed/Under M	1aintenance			
Work is a case of :		New Connectivity/Up gradation/Maintenance				
Sl. No.		Parameters to be checked		Remarks		
1	Pavement	Activities 15				
a)	Road Junctio	n condition		S/U	7-	
b)	Condition of Surfacing			S/U	S	
c)	Riding Quality			S/U	4	
d)	Road Camber			S/U	\(\frac{1}{2}\)	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			√Yes/No	209	
f)	Contraction Joints provided or not (CC Pavement)		√Yes/No	\propto		
g)	Compaction of flank/slope & raincuts if any		√ Yes/No	a		
2	Cross Draina	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	7//	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U	J		
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	×.	
3	Road Furniture			\sim		
a)	Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained			Yes/No	Mo	
4	Compliance l	History				
a)	Status of ATR's & any others		No.			

Overall Rating:	Overa	II R	ating	:
-----------------	-------	------	-------	---

Satisfacory (S)	
Satisfacory but requires Improvement (SRI)	NA.
Unsatisfactory (U)	

NAME: SUKESH KUMAR.
DESIGNATION: A.E.

Signature)