FIELD INSPECTION REPORT

Date of Inspection :		04.12.2020.	District :	MUNG!	ER.	
Division :	Kharey	fur-Tarelpur	Length (Km):	1.850	K·M·	
Name of the Road :		Bandang To2- Goara.				
Scheme/Programme :		MAINTENANCE NEW, MR-3054. Road Id No.: SL. 7. 28,				
Package No. :			Road Id No.:	SL. Ho.	28,	
Status of the Project :		Ongoing/Completed/Under Maintenance				
Work is a case of:		New Connectivity/Up gradation/Maintenance				
Sl. No.		Parameters to be checked	d	Remarks		
1	Pavement					
a)	Road Junctio	n condition		√s/U		
b)	Condition of	ndition of Surfacing		√S/U	S	
c)	Riding Quality		√S/U	4		
d)	Road Camber			√S/U		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		√es/No	ROGR		
f)	Contraction Joints provided or not (CC Pavement)		Yes/No	R		
g)	Compaction of flank/slope & raincuts if any			Yes/No	d	
2	Cross Drainage					
a)	Condition of head walls in Hume pipe culverts including its painting		s/sri/u	N /		
b)	Condition of	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U	1.A.	
c)	Condition of railings/slab/approach for Bridges		S/SRI/U	×		
3	Road Furniture				A	
a)	Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained			Xes/No Logo Brave	Wo	
4	Compliance History					
a)	Status of ATR	s & any others		No		
Overall Rat	ing :	Satisfacory (S)				

Satisfacory (S)	
Satisfacory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: RAM DARSHAN RAM-DESIGNATION: J. E.

(Signature)

3