

FIELD INSPECTION REPORT

Date of Inspection :	04.12.2020	District :	MUNGER.
Division :	Khagapur - Tazipur	Length (Km) :	3.300 Km
Name of the Road :	Raj - Rani Talab Bahalada Road Tazipur		
Scheme Programme :	MAINTENANCE MR-3050 (NEW)		
Package No. :		Road Id No. :	SL-N 52
Status of the Project :	Ongoing ☒ Completed ☐ Under Maintenance ☐		
Work is a case of :	New Connectivity ☐ Up gradation ☐ Maintenance ☐		
Sl. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	☒ S	☐ U
b)	Condition of Surfacing	☒ S	☐ U
c)	Riding Quality	☒ S	☐ U
d)	Road Camber	☒ S	☐ U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	☒ Yes	☐ No
f)	Contraction Joints provided or not (CC Pavement)	☒ Yes	☐ No
g)	Compaction of flank, slope & ruts/cuts if any	☒ Yes	☐ No
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S	SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	NA.
c)	Condition of railings/slab approach for Bridges	S/SRI/U	
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary board Km & 200m zones Pavement road markings are provided and maintained	☒ Yes	☐ No
4	Compliance History		
a)	Status of ATR's & any others	No.	

Overall Rating :

Satisfactory (S) ☒	
Satisfactory but requires Improvement (SRI) ☐	
Unsatisfactory (U) ☐	

NAME : RAM DARSHAN RAM
DESIGNATION : J. E.

R. Darshan Ram
04.12.2020
(Signature)