

FIELD INSPECTION REPORT

Date of Inspection :	04.12.2020	District :	MUNGER.
Division :	Khazagpur - Tazapur	Length (Km) :	1.00 K.M.
Name of the Road :	Barki Hatwiga Gate Se Jatatazi Hill		
Scheme/Programme :	MAINTENANCE NEW. MR-3054		
Package No. :		Road Id No. :	SL No. 18.
Status of the Project :	☒ Ongoing ☐ Completed ☐ Under Maintenance		
Work is a case of :	☒ New Connectivity ☐ Up gradation ☐ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	S/U	PROGRESS
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	WORK IN
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	WORK IN
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained	Yes/No sign board	WORK IN
4	Compliance History		
a)	Status of ATR's & any others	NO	

Overall Rating :

Satisfactory (S)	NA
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: SUKESH KUMAR.
DESIGNATION: A.E.

J. Kew
14-12-2020
(Signature)