

# FIELD INSPECTION REPORT

Date of Inspection :	04.12.2020	District :	MUNGER
Division :	KHARAGPUR-TARAPUR	Length (Km) :	5.620 K.M.
Name of the Road :	Kharagpur - Jamui Raipura Se Sichaikahar hote hue Daripur path		
Scheme/Programme :	MAINTENANCE / O.D. MR(3054)		
Package No. :		Road Id No. :	Project ID- 20803808045
Status of the Project :	Ongoing/Completed/Under Maintenance <input checked="" type="checkbox"/>		
Work is a case of :	New Connectivity/Up gradation/Maintenance <input checked="" type="checkbox"/>		
Sl. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	<input checked="" type="checkbox"/> S/U	
b)	Condition of Surfacing	<input checked="" type="checkbox"/> S/U	
c)	Riding Quality	<input checked="" type="checkbox"/> S/U	
d)	Road Camber	<input checked="" type="checkbox"/> S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	<input checked="" type="checkbox"/> Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	<input checked="" type="checkbox"/> Yes/No	
g)	Compaction of flank/slope & raincuts if any	<input checked="" type="checkbox"/> Yes/No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	N.A.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained	<input checked="" type="checkbox"/> Yes/No	
4	Compliance History		
a)	Status of ATR's & any others	NO.	

Overall Rating :

Satisfactory (S) <input checked="" type="checkbox"/>	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME : SUKESH KUMAR.  
DESIGNATION : A.E.

S. K. Kumar  
04.12.2020  
(Signature)