## FIELD INSPECTION REPORT

Date of Inspection:		04.12.2020.	District :	MUNGER.	
Division :	KHAZA	HPUR- TARAPUR	Length (Km):	0.500 K·M·	
Name of the Road :		Kharagfur-Koudiya Pul (Agaiya hadi) ke Samparak path.			Ke dono. tam
Scheme/Pr	ogramme :	MAINTENANCE			
Package No. :			Road Id No.:	Project ID-	20803808051
Status of the Project :		Ongoing/Completed/Under I	Maintenance	~	
Work is a	case of :	New Connectivity/Up gradat	tion/Maintenance		
Sl. No.			ed	Remarks	
1	Pavement				
a)	Road Juncti	on condition		S/U	
b)	Condition o	f Surfacing		S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	99
e) i	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	p.w
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	10 Q
g)	Compaction of flank/slope & raincuts if any			Yes/No	_ >
2	Cross Drainage				X O
	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	PAKSF1
b) (	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	\$ 0
c) (	Condition of railings/slab/approach for Bridges			S/SRI/U	FX
3 R	Road Furniture				
a) 2	Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained			Yes/No	ROA
	Compliance History				
a) St	Status of ATR's & any others			V/0.	
erall Rating	<u>.</u> :	Satisfacory (S)			
<u> </u>		atisfacory but requires Improvement (SRI)			
Unsatisfactory (U)					

NAME: RAM DARSHAN RAM.
DESIGNATION: J. E.

(Signature)