

FIELD INSPECTION REPORT

Date of Inspection :	04.12.2020	District :	MUMGER.
Division :	KHARAGPUR- TARAPUR	Length (Km) :	2.500 K.M.
Name of the Road :	PWD Kharagpur- Baripada to Bhadoura path		
Scheme/Programme :	MAINTENANCE		
Package No. :		Road Id No. :	Project ID- 202038052
Status of the Project :	Ongoing/Completed/Under Maintenance	✓	
Work is a case of :	New Connectivity/Up gradation/Maintenance	1	
SL No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	✓S/U	
b)	Condition of Surfacing	✓S/U	
c)	Riding Quality	✓S/U	
d)	Road Camber	✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No	
g)	Compaction of flank/slope & raincuts if any	✓Yes/No ✓	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	} N.A.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No	
4	Compliance History		
a)	Status of ATR's & any others	No.	

Overall Rating :

Satisfactory (S)	✓
Satisfactory but requires Improvement (SRI)	✓
Unsatisfactory (U)	

NAME: RAMDARSHAN RAM.
DESIGNATION: J.E.

R.
04.12.2020
(Signature)