FIELD INSPECTION REPORT

Date of	Pate of Inspection: 3-12-2020		District: Jamed	
Division: JHAJHA			Length (km): 4.020	
			is PND road to Kuraw	via Genadin.
	:/Programme:	MAINTENANCE	(New maintenance)	
		5000/61/VHr	Read Id No.: 2080410101	2,
Status of the Project: Ongoing/Completed				
Work is a case of:		New Connectivity/Up gradation/ Maintenance		
Sl. No.		Parameters to	be checked	Remarks
1.	Pavement		of Parket and the	
a)	Road Junction condition			S/U N/A
b)	Condition of Surfacing			S/U N/A
c)	Riding Quality			S/U N/A.
d)	Road Camber			S/U T/A.
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No NA.
Ŋ	Contraction Joints provided or not (CC Pavement)			Yes/No NA.
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U N/A ·
c)	Condition of railings/slab/approach for Bridges			S/SRI/U N/A
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No (Partially)
4.	Compliance His	story		
a)	Status of ATR's	& any others		NO

Overall Rating

Satisfactory (S)	's'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature) 1.6.

NAME: Kabilekh Kumor

DESIGNATION: J.E.