

FIELD INSPECTION REPORT

Date of Inspection :	3.12.2020	District:	Tamir
Division :	Jhatha	Length (km):	2.800km
Name of the Road:	Dadpur Bawa p.w.D. Road to Kita Kusana		
Scheme/Programme:	MAINTENANCE	New maintenance.	
Package No.:	RM/JA/JHA/19/0016	Road Id No.:	20804101030
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	N/A S/U
b)	Condition of Surfacing	N/A S/U
c)	Riding Quality	N/A S/U
d)	Road Camber	N/A S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A Yes/No
f)	Contraction Joints provided or not (CC Pavement)	N/A Yes/No
g)	Compaction of flank/slope & raincuts if any	N/A Yes/No
2.	Cross Drainage	N/A
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N/A S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	N/A
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

work not started

NAME:- NATHUNI SINGH

A.E.
Jhale

3-12-2020
(Signature)