

FIELD INSPECTION REPORT

Date of Inspection :	3.12.2020	District:	Jamui
Division :	JHATHA	Length (km):	2.800 Km
Name of the Road:	Borwa - Panamwa path		
Scheme/Programme:	MAINTENANCE New maintain.		
Package No.: Rm/JA	JHA/19/0025	Road Id No.:	208041 02043
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	H/A S/U
b)	Condition of Surfacing	H/A S/U
c)	Riding Quality	H/A S/U
d)	Road Camber	H/A S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	H/A Yes/No
f)	Contraction Joints provided or not (CC Pavement)	H/A Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	H/A SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	H/A S/SRI/U
c)	Condition of railings/slab/approach for Bridges	H/A S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Earthwork started

NAME:

Nathuram Singh
A E
Jhatha.


3.12.2020
(Signature)