

FIELD INSPECTION REPORT

Date of Inspection :	3-12-2020	District:	Jammu
Division :	Jhatha	Length (km):	1.240 km
Name of the Road:	Harhawa to Sidhelari		
Scheme/Programme:	MAINTENANCE	New maintainance.	
Package No.:	Rm) JA/JHA/19/0018	Road Id No.:	20804102055
Status of the Project:	<input checked="" type="checkbox"/> Ongoing/ <input type="checkbox"/> Completed/ <input type="checkbox"/> Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	H/A Yes/No
f)	Contraction Joints provided or not (CC Pavement)	H/A Yes/No
g)	Compaction of flank/slope & raincuts if any	H/A Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	H/A S/SRI/U
c)	Condition of railings/slab/approach for Bridges	H/A S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


3-12-2020
(Signature)

NAME: NATHUM SINGH
A - E
JHATHA