## FIELD INSPECTION REPORT

Date of Inspection: 3-12-2020			District: Jamui		
Division: JHAJHA			Length (km): 3.91		
Name	e of the Road: S	alaia to Leixi			
	ne/Programme:	MAINTENANCE	(New maintenance		
		5000 61 H	Road Id No.: 208041020		
	s of the Project:		I/Under Maintenance (Work	has been	sh
V Lat Late	is a case of:	New Connectivity/U	Jp gradation/ Maintenance		
Sl. No	0.	Parameters to	nmeters to be checked Remark		S
1.	Pavement				
a)	Road Junction			S/U	H
b)	Condition of Su	Condition of Surfacing			N
c)	Riding Quality			S/U	N
d)	Road Camber			S/U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	_
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	N
g)	Compaction of flank/slope & raincuts if any			Yes/No	^
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	1
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	-
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	_
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained  Yes/No				
4.	Compliance Hist				
1)	Status of ATR's &	& any others		No	31

Overall Rating

Satisfactory (S)	·
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	-
	1 1

(Signature) 16.

NAME: Kabilekh Kumor

DESIGNATION: 18.