## FIELD INSPECTION REPORT

	f Inspection 1	05 12 2020	District: Jamui		
Division: Jamui			Length (km): 1.00 KM		
	of the Road: Jo	amui Lakhisara	i P.W.D Road to MariNaga	eron	
Schem	e/Programme:	MAINTENANCE		0.71	
Status	ge No.: XIA	10110	Road Id No.: 20804/08/	59	
			Ongoing/Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance		
\$1. No.	10.72	Paramoters		THE PERSON NAMED IN	
	Pavement	A STATE OF THE STA	o be edecked	Remarks	
a)	Road Junction	condition		SZU	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2	Cross-Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			8/SRI/U-	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			-S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3	Road Furnitur	o disco			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4	recompilence us	istory	CANTER AND THE PERSON		
a)	Status of ATR's	& any others		AKN	

Overall Rating

Satisfactory (S)	1 2
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	107

Justo 4 9 09/12/2020

(Signature)

NAME: