FIELD INSPECTION REPORT

ate of Inspection: 5/12/100			District: Tamui		
Division: Jamui			Length (km): Q.4 V to		
ame of the Ro	id: Haw	Kedih Rawa	i Mushari TO Lachhuar r	Dud	
mornior rogia	nme: M	AINTENANC	E	0-14	
ackage No.:	·		Road Id No.:		
atus of the Pr		ngoing/Comple	eted/Under Maintenance		
ork is a case		ew Connectivit	ty/Up gradation/ Maintenance		
Inno: Paye		Parameter	to of died ad	Remarks	
Pave	ent				
a) Road	Road Junction condition				
	Condition of Surfacing				
	Riding Quality			√8/U	
	Road Camber			√S/U	
e) Whet aggre	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				
f) Contr	Contraction Joints provided or not (CC Pavement)				
g) Comp	Compaction of flank/slope & raincuts if any				
Para (Cio	Deninage			¥es/No	
a) Cond	Condition of head walls in Hume pipe culverts including its painting S/SPI/U				
	Condition of Abutment & Wing walls, Slab in RCC culverts				
	Condition of railings/slab/approach for Bridges			_ S/SRI/U _ S/SRI/U	
THE RESERVE OF THE PARTY OF THE	Furniture	The state of the s			
Whet	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
a) stone				Yes/No	
A DECEMBER OF THE	compliance in the second se				
a) Status	Status of ATR's & any others			- L/A	

Overall Rating

Satisfactory (S)	,
Satisfactory but requires Improvement (SRI)	5.0.7
Unsatisfactory (U)	10.12.1
	/#:

105-12-20

A. E. 112/10

Executive Engineer RVRIENATION Division, Jamui

NAME:

DESIGNATION: