

FIELD INSPECTION REPORT

Date of Inspection : 08.12.2020		District: Sahyadra
Division : Sahyadra		Length (km): 1.80 km
Name of the Road: Malawi Chowk to Tanashtan		
Scheme/Programme: MAINTENANCE		
Package No: 05 WPD/2015-16 Road Id No:		
Status of the Project: Ongoing/Completed/Under Maintenance		
Work in a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
Pavement		
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
Road Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SR/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SR/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SR/U
Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
Accident History		
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Note: 1.5 kilometer and 200 m stone required to fix.

NAME: Ravi Shankar Kumar
DESIGNATION: Junior Engineer

(Signature)
08/12/2020