

FIELD INSPECTION REPORT

Date of Inspection :- 21.12.20	District :- Raigarh	
Division :- Khairatabad	Length (km) :- 9.810	
Name of Road :- Ghat Mahanad Road to Puliyandi		
Scheme / Programme :- D/S (State N.R.)	Maintenance	
Package No. :-	Road ID No. :-	
Status of Project :- <i>Complete</i>	Ongoing/Complete/Under Maintenance	
Work is a case of :- <i>Surface damage</i>	New Connectivity/Upgradation/Maintenance	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction Condition	S/U
b)	Condition of Surface	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No
f)	Construction joints provided or not (CC Pavement)	Yes/No
g)	Comparison of Bank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	S/SRI/U
c)	Condition of railings, slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200 m stone/Pavement road markings are provided and maintained	Yes Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No.

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

3.12.20
5-E/puliyandi