## FIELD INSPECTION REPORT

2.12.2020	District: Khagazia
	Length (km): 2,600km
rigation Bar	ndh - Khaizaitha
MAINTENANCE	NEW 3054 MR
Commence of the Commence of th	Road Id No.:
Ongoing/Completed/Under Maintenance	
New Connectivity/Up gradation/ Maintenance	
	oigation for MAINTENANCE Ongoing/Completed

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	√S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No 14
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	s/sri/u )
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	The state of the s

Overall Rating

Satisfactory (S)	Q
Satisfactory but requires Improvement (SRI)	_
Unsatisfactory (U)	

NAME:

DESIGNATION

(Signature)