FIELD INSPECTION REPORT

75.6		The state of the s			
Date of Inspection: 05.12.2020 District: Khagania					
Division			gth (km): 04.05 Km	2:	
and the second	the Roads O	Karna to cha	Kprayago		
-	Programme:		d Id No.:		
Package	Committee of the second	Ongoing/Completed/Undo			
			Jp gradation/ Maintenance		
		Parameters to be ch	Annual Company of the		
1.	Pavement				
a)	20.42	ad Junction condition			•
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No] H.A
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	1
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	NA
, c)	Condition of railings/slab/approach for Bridges			S/SRI/U_	1
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	MA
4.	Compliance History				
a) -	Status of ATR's & any others				
* O11	D	Market State of the Control of the C			
Overall	Kanng :	Satisfactory (S)		A SECTION OF THE PROPERTY OF THE PARTY OF TH	
		Satisfactory but requi	res Improvement (SRI)	and the second	
		Unsatisfactory (U)			

NOTE - WARK in Progress.

(Signature) 32020.

NAME: AKWICH Kumon DESIGNATION: ASH: Englinean