

FIELD INSPECTION REPORT

Date of Inspection :- 3.12.20		District :- Mahasana	
Division :- Mahasana		Length (Km) :- 4.450	
Name of Road :- Ghuhariyat se Mahasana path			
Scheme/Programme :- M.R.-old		Maintenance	
Package No. :-		Road ID No. :-	
Status of Project :- <u>Completed</u>		Ongoing/Complete/Under Maintenance <u>✓</u>	
Work is a case of :-		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction Condition	S S/U	
b)	Condition of Surface	S S/U	
c)	Riding Quality	S S/U	
d)	Road Camber	S S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	No Yes/No	
f)	Construction joints provided or not (CC Pavement)	Yes Yes/No	
g)	Compaction of flank/slope & raincuts if any	No Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	M.A. S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	M.A S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200 m stone/Pavement road markings are provided and maintained	Yes Yes/No	
4.	Compliance History		
a)	Status of ATRs & any others	No	

Overall Rating:

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature) ku
3.12.20
J-E/Alau