FIELD INSPECTION REPORT

ate of Inspection: Q3/12.2020 District: Khangaia				
ame of	the Road: 1810	BALL BE BOKK	Length (km): 1.400 km read 9400 kabel 3 8699 via Coll. Bardh to mured	at willa
	rogramme:	MAINTENANCE	NEW 3024 MIV	
ackage No.:			Road Id No.:	
-	the Project:		/Completed/Under Maintenance	
M. San September 1	a case of:	A Marie Monate (Chapter of the Company of the Company	//Up gradation/ Maintenance	erran englisher
Sl. No.		Parameters	to be checked	Remarks
i	Pavement			
a)	Road Junction condition			S/U
b) .	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No~
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drain	age		
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance History			
a)	Status of A7	Status of ATR's & any others		
0	Il Dating			a company of the second
Overall Rating :		Satisfactory		2
y.			but requires Improvement (SRI)	
		Unsatisfacto	ry (U)	1

(Signature)

NAME:

DESIGNATION: 63.

63.12.2020 63.12.2020 ARIMOJ 3112/2020