FIELD INSPECTION REPORT

Date of Inspection : 2/12/2020 District: KHAGARIA				
Division: GOGRI			Length (km):	
and the second		auakol mo	RE 'SE GOGRI' BAZAI	٤
The state of the s	Programme:	MAINTENANCE	The state of the s	
Package	The second secon	TA TAKE	Road Id No.: ed/Under Maintenance	
Work is a case of: New Connectivi		Ongoing/Complete	y/Up gradation/ Maintenance	
		Parameters to be checked		Remarks
Sl. No.		Parameters t	o pe checked	
1.	Pavement VS/U			
a)	Road Junction condition			
b)	Condition of Surfacing			S/U~
c)	Riding Quality			· S/UV
	Road Camber			~S/U
d) e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
Ð	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SKI/U
4 114	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
b)	Condition of railings/slab/approach for Bridges			S/SRI/U
c)	Road Furniture			
3.	2	Carlot and the control of the carlot and the carlot	2 11 0 200	V
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
4.	Compliance History			
a)	Status of ATR's & any others			

Overall Rating

Satisfactory (S)	•
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	Unsatisfactory

NAME:

DESIGNATION:

oz.12.2020

Maney Kr. Sargam

Junior Ezgineer

(Signature)