

FIELD INSPECTION REPORT

Date of Inspection : 02-12-20		District: Supaul	
Division : Vispm		Length (km): 3.100	
Name of the Road: Pratab Garh chhatapur chaur Jinter			
Scheme/Programme: MAINTENANCE		Road Id No.: SL.M..1343(19-20)	
Package No.:		Status of the Project: Ongoing/Completed/Under Maintenance Ongoing	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		S/U
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Drainage		S/SRI/U
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		S/SRI/U
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4.	Compliance History		S/SRI/U
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Note:- Work is not started till date.

[Signature]
02/12/20
(Signature)

NAME: Shri Nandani P. Kumar
A.B. (Pratab Garh)