

# FIELD INSPECTION REPORT

Date of Inspection: 02.12.2020	District: Supaul
Division: Supaul	Length (km): 5.400
Name of the Road: P.W.D. Dudhaura Malikana To Baliyas Road	
Scheme/Programme:	MAINTENANCE
Package No.:	Road Id No.: 21004908063
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N.A.
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N.A.
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N.A.
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	Not Required

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	✓
Unsatisfactory (U)	

*R/b*  
02.12.2020  
(Signature)

NAME: Ran Vijay Kumar  
DESIGNATION: A.E., R.W.D., Supaul