## FIELD INSPECTION REPORT

Date of I	nspection:	02.19.2020 District: Supaul		
Division: Supaul Length (km): 0.700			)	
Name of the Road: कर्ण पर राजनपुर पथ से अहमपुर होते हुए विरो हार तक सड़कीन				
	Programme		V = 0 11 2 11 2 1	
		Road Id No.:		
Status of the Project: Ongoing/Completed/Under Maintenance				
Work is a case of: New Connectivity/Up gradation/ Maintenance				
Sl. No.		Parameters to be checked	Remarks	
1.	Pavement			
a)	Road Junct	ion condition	S/U	
b)	Condition	of Surfacing	S/U	
c)	Riding Qua	ality	S/U	
d)	Road Cam	ber V	S/U	
e)	Whether aggregates	free from defects such as visible cracks, ex in case of CC Pavement.	posed Yes/No	
f)	Contraction	n Joints provided on not (CC Pavement)	Yes/No	
g)	Compactio	n of flank/stone & raincuts if any	Yes/No	
<b>2.</b>	Cross Drainage			
a)	Condition	of lead walls in Hume pipe culverts including its pa	inting S/SRI/U	
b)	Condition	of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition	of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furi	niture		
a)		ign boards/informatory/cautionary Board/km & ement road markings are provided and maintained	200m Yes/No	
4.	Complian	ee History		
a)	Status of A	TR's & any others		
0 "				

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

02.12.2020 (Signature)

NAME: Ran Vijay Kumar DESIGNATION: A.E., R.W.D., Sufaul

Scanned by CamScanner