## **FIELD INSPECTION REPORT**

Date of Inspection: 03-12-2020 District: Kishangang  Name of the Road: Bhogshowki to Bhologoni  Scheme/Programme: MAINTENANCE  Package No.: Rm KT KIS 19 0004 Road Id No.:  Status of the Project: Ongoing/Completed /Under Maintenance - N. A (under Philosy T)  Work is a case of: New Connectivity/ Up gradation / Maintenance  1. Pavement  a) Road Junction Condition  b) Condition of Surfacing  C) Riding Quality  d) Road Camber  e) Whether free from defects such as visible cracks, exposed aggregates yes/No in case of CC Pavement.  f) Contraction Joints Provided or not (CC Pavement)  g) Compaction of flank / slope & raincuts if any  2. Cross Drainage  a) Condition of Abutment & Wing walls, slab in RCC culverts  c) Condition of railings/Slab/approach for Bridges  3. Road Furniture  a) Whether sign boards/informatory/cautionary Board/km & 200m  N-A- Yes/No stones/Pavement road markings are provided and maintained  4. Compliance History			FIELD IN	SPECTION REPORT			
Name of the Road: Bhog showki to Chelogoni Scheme/Programme: MAINTENANCE Package No.: Rm kt kts 19 0004 Road Id No.: Status of the Project: Ongoing/Completed /Under Maintenance - N · A (under PMoSyT) Work is a case of: New Connectivity/ Up gradation / Maintenance St. No Parameters to be checked  1. Pavement a) Road Junction Condition b) Condition of Surfacing Takem UP PMGSY S/U c) Riding Quality d) Road Camber e) Whether free from defects such as visible cracks, exposed aggregates yes/No in case of CC Pavement. f) Contraction Joints Provided or not (CC Pavement) g) Compaction of flank / slope & raincuts if any 2. Cross Drainage a) Condition of head walls in Hume pipe culverts including its Painting S/SRI/U b) Condition of Abutment & Wing walls, slab in RCC culverts c) Condition of railings/Slab/approach for Bridges 3. Road Furniture a) Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained 4. Compliance History	Date of	Inspection: 02	10			-	
Cheme/Programme: MAINTENANCE  Package No.: Rm KI KIS 19 004 Road Id No.:  Status of the Project: Ongoing/Completed /Under Maintenance - N A (Under PMISSAT)  Work is a case of: New Connectivity/ Up gradation / Maintenance  1. Pavement  a) Road Junction Condition  b) Condition of Surfacing  c) Riding Quality  d) Road Camber  e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.  f) Contraction Joints Provided or not (CC Pavement)  g) Compaction of flank / slope & raincuts if any  2. Cross Drainage  a) Condition of Abutment & Wing walls, slab in RCC culverts  C) Condition of railings/Slab/approach for Bridges  3. Road Furniture  a) Whether sign boards/informatory/cautionary Board/km & 200m  stones/Pavement road markings are provided and maintained  4. Compliance History	Division	: Kishama a	-12-2020				
Package No.: RM KI KIS 19 0004 Road Id No.:  Status of the Project: Ongoing/Completed /Under Maintenance — N. A (Under PMGSY-II)  Work is a case of: New Connectivity/ Up gradation / Maintenance  1. Pavement  a) Road Junction Condition  b) Condition of Surfacing  c) Riding Quality  d) Road Camber  e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.  f) Contraction Joints Provided or not (CC Pavement)  g) Compaction of flank / slope & raincuts if any  2. Cross Drainage  a) Condition of Abutment & Wing walls, slab in RCC culverts  c) Condition of railings/Slab/approach for Bridges  3. Road Furniture  a) Whether sign boards/informatory/cautionary Board/km & 200m  Yes/No	Name of the Road: St. Length(km): 6.0						
Status of the Project: Ongoing/Completed /Under Maintenance — N. A. (Under Project)  Work is a case of: New Connectivity/ Up gradation / Maintenance  1. Pavement  a) Road Junction Condition  b) Condition of Surfacing  c) Riding Quality  d) Road Camber  e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.  f) Contraction Joints Provided or not (CC Pavement)  g) Compaction of flank / slope & raincuts if any  2. Cross Drainage  a) Condition of Abutment & Wing walls, slab in RCC culverts  c) Condition of railings/Slab/approach for Bridges  3. Road Furniture  a) Whether sign boards/informatory/cautionary Board/km & 200m  Yes/No  Yes/No  Yes/No  Yes/No  Yes/No  S/SRI/U  S/SRI/U  S/SRI/U  Compliance History	Scheme	/Programme:	and I properly to	Bhelaguri			
Status of the Project: Ongoing/Completed /Under Maintenance — N. A (Under PMGS/II) Work is a case of: New Connectivity/ Up gradation / Maintenance  1. Pavement a) Road Junction Condition b) Condition of Surfacing C) Riding Quality d) Road Camber e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. f) Contraction Joints Provided or not (CC Pavement) g) Compaction of flank / slope & raincuts if any 2. Cross Drainage a) Condition of Abutment & Wing walls, slab in RCC culverts C) Condition of railings/Slab/approach for Bridges 3. Road Furniture a) Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained 4. Compliance History							
Work is a case of:  New Connectivity/ Up gradation / Maintenance  1. Pavement  a) Road Junction Condition  b) Condition of Surfacing  c) Riding Quality  d) Road Camber  e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.  f) Contraction Joints Provided or not (CC Pavement)  g) Compaction of flank / slope & raincuts if any  2. Cross Drainage  a) Condition of head walls in Hume pipe culverts including its Painting  b) Condition of Abutment & Wing walls, slab in RCC culverts  c) Condition of railings/Slab/approach for Bridges  3. Road Furniture  a) Whether sign boards/informatory/cautionary Board/km & 200m  stones/Pavement road markings are provided and maintained  4. Compliance History	Status o	of the Project:	1   KIS   19   0	Road Id No.:	nco - N.A (	Lond	or DIMOCKT
1. Pavement a) Road Junction Condition b) Condition of Surfacing c) Riding Quality d) Road Camber e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. f) Contraction Joints Provided or not (CC Pavement) g) Compaction of flank / slope & raincuts if any 2. Cross Drainage a) Condition of Abutment & Wing walls, slab in RCC culverts c) Condition of railings/Slab/approach for Bridges 3. Road Furniture a) Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained 4. Compliance History	Work:						
1. Pavement a) Road Junction Condition b) Condition of Surfacing c) Riding Quality d) Road Camber e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. f) Contraction Joints Provided or not (CC Pavement) g) Compaction of flank / slope & raincuts if any 2. Cross Drainage a) Condition of head walls in Hume pipe culverts including its Painting b) Condition of Abutment & Wing walls, slab in RCC culverts c) Condition of railings/Slab/approach for Bridges 3. Road Furniture a) Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained 4. Compliance History	S1. No	The commentation of the comment of t					
a) Road Junction Condition b) Condition of Surfacing c) Riding Quality d) Road Camber e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. f) Contraction Joints Provided or not (CC Pavement) g) Compaction of flank / slope & raincuts if any Condition of head walls in Hume pipe culverts including its Painting Condition of Abutment & Wing walls, slab in RCC culverts c) Condition of railings/Slab/approach for Bridges 3. Road Furniture a) Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained 4. Compliance History	1.	Farameters to be checked					
b) Condition of Surfacing  c) Riding Quality d) Road Camber e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. f) Contraction Joints Provided or not (CC Pavement) g) Compaction of flank / slope & raincuts if any  Condition of head walls in Hume pipe culverts including its Painting S/SRI/U b) Condition of Abutment & Wing walls, slab in RCC culverts Condition of railings/Slab/approach for Bridges  Road Furniture  Whether sign boards/informatory/cautionary Board/km & 200m Stones/Pavement road markings are provided and maintained  Compliance History							S/II
c) Riding Quality d) Road Camber S/U e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. f) Contraction Joints Provided or not (CC Pavement) Yes/No Compaction of flank / slope & raincuts if any Yes/No Cross Drainage a) Condition of head walls in Hume pipe culverts including its Painting Condition of Abutment & Wing walls, slab in RCC culverts Condition of railings/Slab/approach for Bridges S/SRI/U Condition of railings/Slab/approach for Bridges Whether sign boards/informatory/cautionary Board/km & 200m Stones/Pavement road markings are provided and maintained  4. Compliance History		Condition of Surface Takem UP PM 615Y - 2					
d) Road Camber  e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.  f) Contraction Joints Provided or not (CC Pavement)  g) Compaction of flank / slope & raincuts if any  2. Cross Drainage  a) Condition of head walls in Hume pipe culverts including its Painting  b) Condition of Abutment & Wing walls, slab in RCC culverts  c) Condition of railings/Slab/approach for Bridges  3. Road Furniture  a) Whether sign boards/informatory/cautionary Board/km & 200m  stones/Pavement road markings are provided and maintained  4. Compliance History							
e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.  f) Contraction Joints Provided or not ( CC Pavement) Yes/No  g) Compaction of flank / slope & raincuts if any Yes/No  2. Cross Drainage  a) Condition of head walls in Hume pipe culverts including its Painting S/SRI/U  b) Condition of Abutment & Wing walls, slab in RCC culverts S/SRI/U  c) Condition of railings/Slab/approach for Bridges S/SRI/U  3. Road Furniture  a) Whether sign boards/informatory/cautionary Board/km & 200m Yes/No  stones/Pavement road markings are provided and maintained  4. Compliance History							
in case of CC Pavement.  f) Contraction Joints Provided or not ( CC Pavement)  g) Compaction of flank / slope & raincuts if any  2. Cross Drainage  a) Condition of head walls in Hume pipe culverts including its Painting  b) Condition of Abutment & Wing walls, slab in RCC culverts  c) Condition of railings/Slab/approach for Bridges  3. Road Furniture  a) Whether sign boards/informatory/cautionary Board/km & 200m  stones/Pavement road markings are provided and maintained  4. Compliance History							
f) Contraction Joints Provided or not ( CC Pavement)  g) Compaction of flank / slope & raincuts if any  2. Cross Drainage  a) Condition of head walls in Hume pipe culverts including its Painting S/SRI/U  b) Condition of Abutment & Wing walls, slab in RCC culverts  c) Condition of railings/Slab/approach for Bridges  3. Road Furniture  a) Whether sign boards/informatory/cautionary Board/km & 200m  Syski/U  Yes/No  Yes/No  Yes/No  Yes/No  Compliance History	٠,	Whether free from defects such as visible crucks, exposed against					
g) Compaction of flank / slope & raincuts if any  2. Cross Drainage  a) Condition of head walls in Hume pipe culverts including its Painting S/SRI/U  b) Condition of Abutment & Wing walls, slab in RCC culverts  c) Condition of railings/Slab/approach for Bridges  3. Road Furniture  a) Whether sign boards/informatory/cautionary Board/km & 200m  Yes/No  Yes/No  Yes/No  Yes/No  Yes/No	f)						Yes/No
2. Cross Drainage  a) Condition of head walls in Hume pipe culverts including its Painting S/SRI/U  b) Condition of Abutment & Wing walls, slab in RCC culverts S/SRI/U  c) Condition of railings/Slab/approach for Bridges S/SRI/U  3. Road Furniture  a) Whether sign boards/informatory/cautionary Board/km & 200m Yes/No stones/Pavement road markings are provided and maintained  4. Compliance History							
a) Condition of head walls in Hume pipe culverts including its Painting S/SRI/U b) Condition of Abutment & Wing walls, slab in RCC culverts S/SRI/U c) Condition of railings/Slab/approach for Bridges S/SRI/U  3. Road Furniture a) Whether sign boards/informatory/cautionary Board/km & 200m Yes/No stones/Pavement road markings are provided and maintained 4. Compliance History		compaction of mank/ slope & familiars in any					
b) Condition of Abutment & Wing walls, slab in RCC culverts  c) Condition of railings/Slab/approach for Bridges  3. Road Furniture  a) Whether sign boards/informatory/cautionary Board/km & 200m  stones/Pavement road markings are provided and maintained  4. Compliance History							S/SRI/U
c) Condition of railings/Slab/approach for Bridges  3. Road Furniture  a) Whether sign boards/informatory/cautionary Board/km & 200m  stones/Pavement road markings are provided and maintained  4. Compliance History							
3. Road Furniture  a) Whether sign boards/informatory/cautionary Board/km & 200m Yes/No stones/Pavement road markings are provided and maintained  4. Compliance History							
a) Whether sign boards/informatory/cautionary Board/km & 200m Yes/No stones/Pavement road markings are provided and maintained  4. Compliance History		Condition of family approach to English					
stones/Pavement road markings are provided and maintained  4. Compliance History		Vos/No					
4. Compliance History	aj						
	4.						
a) Status of ATR's & any others	a)	Status of ATR's			No	AT	R pondity

Overall Rating:

Satisfactory(S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory(U)

—

Road is being constructed under PMMSY-II

NAME: Sonjaer Kumor pasuson.

J. E Terhagachh.

T.∈ R.W.D (W) Division
Kishanganj-1