

FIELD INSPECTION REPORT

Date of Inspection: 02-3-2020		District: Kishanganj	
Division: Kishanganj-1		Length(km): 2.950	
Name of the Road: To2 - Miapur.			
Scheme/Programme:		MAINTENANCE	
Package No.: RM/KI/KIS/19/0013		Road Id No.:	
Status of the Project:		Ongoing/Completed /Under Maintenance 21205802063	
Work is a case of:		New Connectivity/ Up gradation / Maintenance	
S1. No	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction Condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints Provided or not (CC Pavement)		Yes/No
g)	Compaction of flank / slope & raincuts if any		Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its Painting		S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts		S/SRI/U
c)	Condition of railings/Slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		No ATR pending

Overall Rating :

Satisfactory(S)	"S"
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory(U)	—

NAME: Sanjeev Kumar Prasad
J.E Terhagachh.

Sanj
02/3/2020
J.E R.W.D (W) Division
Kishanganj-1