## FIELD INSPECTION REPORT

Date of Inspection: - 03-12-20 District: - Kis hampanj Division: - Kishangani-I Length(km): 3.500 Name of the Road: L.R.P to chandwar via shokarpat Scheme/Programme: - constructing under PMGSY-II) **MAINTENANCE** Package No .: - NIA Road Id No .: Status of the Project: Ongoing/Completed / Under Maintenance - N.A (under pmgsy-II Work is a case of: New Connectivity/ Up gradation / Maintenance \$1. No Parameters to be checked Remarks 1. **Pavement** a) Road Junction Condition S/U b) Condition of Surfacing A. W S/U c) Riding Quality S/U d) Road Camber S/U Whether free from defects such as visible cracks, exposed aggregates e) Yes/No in case of CC Pavement. Contraction Joints Provided or not (CC Pavement) f) Yes/No N. A Compaction of flank / slope & raincuts if any g) Yes/No 2. **Cross Drainage** Condition of head walls in Hume pipe culverts including its Painting NA a) S/SRI/U b) Condition of Abutment & Wing walls, slab in RCC culverts S/SRI/U Condition of railings/Slab/approach for Bridges c) S/SRI/U 3. **Road Furniture** Whether sign boards/informatory/cautionary Board/km & 200m? a) stones/Pavement road markings are provided and maintained Yes/No N. A 4. **Compliance History** Status of ATR's & any others a)

Overall Rating :- N'A

Satisfactory(S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory(U)

Road is being constructed under PMGSY-II

NAME: Er. Radheshyano prograpati

تروز (W) Division Kishanganj-1