FIELD INSPECTION REPORT

District: - Kizhangani Date of Inspection: - 63-12-20 Division: - Kishangany-I Length(km): 2100 Dangaron to Laucha Name of the Road: Bahadurgany MAINTENANCE Scheme/Programme: Road Id No.: Package No.: - N A Ongoing/Completed / Under Maintenance (Transferred to RCA) Status of the Project: New Connectivity/ Up gradation / Maintenance Work is a case of: S1. No Parameters to be checked Remarks 1. **Pavement** Road Junction Condition a) S/U Condition of Surfacing b) NIA S/U c) Riding Quality S/U d) Road Camber S/U Whether free from defects such as visible cracks, exposed aggregates e) Yes/No in case of CC Pavement. - NIA Contraction Joints Provided or not (CC Pavement) - N.A f) Yes/No Compaction of flank / slope & raincuts if any _ NA g) Yes/No **Cross Drainage** 2. Condition of head walls in Hume pipe culverts including its Painting -N-A a) S/SRI/U Condition of Abutment & Wing walls, slab in RCC culverts b) S/SRI/U Condition of railings/Slab/approach for Bridges c) NIA S/SRI/U 3. Road Furniture Whether sign boards/informatory/cautionary Board/km & 200m a) Yes/No stones/Pavement road markings are provided and maintained - N · A 4. **Compliance History** Status of ATR's & any others a) - NO pendig ATR

Overall Rating : N'A

Satisfactory(S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	_

femons - Road is transferred to RCD

NAME: - Er. Radheshyam prajapati

R.W.D (W) Division
Kishanganj-1