FIELD INSPECTION REPORT

ate of Inspection: - 03-12-20 District: - Kishorngomi Division: - Kizhangany . I Length(km): 3.60 Name of the Road: Bahadurgany to Bhatlawara Scheme/Programme: **MAINTENANCE** Package No.: Road Id No .: Status of the Project: (constructing winder PMBsy 1) Ongoing/Completed /Under Maintenance Work is a case of: New Connectivity/ Up gradation / Maintenance - N · A \$1. No Parameters to be checked Remarks 1. **Pavement** Road Junction Condition a) S/U b) Condition of Surfacing S/U A'M c) Riding Quality S/U d) Road Camber S/U Whether free from defects such as visible cracks, exposed aggregates e) Yes/No in case of CC Pavement. - N A f) Contraction Joints Provided or not (CC Pavement) Yes/No N.A g) Compaction of flank / slope & raincuts if any Yes/No 2. **Cross Drainage** Condition of head walls in Hume pipe culverts including its Painting - N'A a) S/SRI/U Condition of Abutment & Wing walls, slab in RCC culverts? b) S/SRI/U N.A c) Condition of railings/Slab/approach for Bridges S/SRI/U **Road Furniture** 3. Whether sign boards/informatory/cautionary Board/km & 200m a) Yes/No stones/Pavement road markings are provided and maintained - N · A 4. Compliance History a) Status of ATR's & any others - N.A

Overall Rating : N.A

Satisfactory(S)	-
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	_

Remorts - Road is being construted under projecy. I

NAME: - Er. Radheshyam prajapati

R.W.D (W) Division
Kishanganj-1