

FIELD INSPECTION REPORT

Date of Inspection: 3/12/2020		District: Kishanganj
Division: Kishanganj-1		Length(km):
Name of the Road: Ayra Garh Bihar Border to Bastadangi		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.: 21205808059
Status of the Project:		Ongoing/Completed /Under Maintenance (Out of Maintenance)
Work is a case of:		New Connectivity/ Up gradation / Maintenance

Sl. No	Parameters to be checked	Remarks
1.	Pavement	S/U
a)	Road Junction Condition	out of Maintenance S/U
b)	Condition of Surfacing	Then taken up in S/U NA
c)	Riding Quality	FD Rg Maint Period. S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints Provided or not (CC Pavement)	Yes/No
g)	Compaction of fland / shop & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its Painting	S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts	NA S/SRI/U
c)	Condition of railings/Slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No ATR

Overall Rating :

Satisfactory(S)	NA
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory(U)	-


 3/12/20
 (Signature)

NAME:

AE