FIELD INSPECTION REPORT

Date of Inspection: 3 12 2020 District: Kishangani			
Division: Kishangam 1 Length(km): 3.0 km			
Name of the Road: Kanhaiya Bani to Yalli hani			
Scheme/Programme: MAINTENANCE			
Package No.: - Road Id No.: 212.05808060			
Status of the Project: Ongoing/Completed / Under Maintenance Out of Maintenance			
Work is a case of: New Connectivity/ Up gradation / Maintenance			
\$1. No	Parameters to be checked		Remarks
1.	Davoment		S/U
a)	Road Junction Condition	out of Maintenance.	s/U
b)	Condition of Surfacing	2) Alignment taken in PMGSY	S/U
c)	Riding Quality	I for widening.	S/U
d)	Road Camber	5	S/U
e)	-	such as visible cracks, exposed aggregates	Yes/No
-,	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
f)	Contraction Joints Provided or not (CC Pavement) Yes/No		
g)	Compaction of fland / shop & raincuts if any		Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its Painting S/SRI/L		
b)	Condition of Abutment & Wing walls, slab in RCC culverts		
c)	Condition of Abdument & Wing Wans, slab in Rec culverts Condition of railings/Slab/approach for Bridges		s/sri/U
3.	Road Furniture		
	7		
a)	Whether sign boards/informatory/cautionary Board/km & 200m Yes/No stones/Pavement road markings are provided and maintained		
4.	Compliance History		
	Status of ATR's & any others		NOATR
a)	Status of ATR's & any others		MOTH

Overall Rating:

Satisfactory(S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory(U)

(Signature)

NAME:

AE