

## FIELD INSPECTION REPORT


Date of Inspection: - 03.12.20		District: - Kishanganj	
Division: - Kishanganj-I		Length(km): 5.50 km	
Name of the Road: Bahadurganj to Bhatbari			
Scheme/Programme:		MAINTENANCE	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed /Under Maintenance (Constructing under PMGSY-II)	
Work is a case of:		New Connectivity/ Up gradation / Maintenance	
Sl. No	Parameters to be checked	Remarks	
1.	<b>Pavement</b>		
a)	Road Junction Condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. N.A	Yes/No	
f)	Contraction Joints Provided or not ( CC Pavement)	Yes/No	
g)	Compaction of flank / slope & raincuts if any	Yes/No	
2.	<b>Cross Drainage</b>		
a)	Condition of head walls in Hume pipe culverts including its Painting - N.A	S/SRI/U	
b)	Condition of Abutment & Wing walls, slab in RCC culverts	S/SRI/U	
c)	Condition of railings/Slab/approach for Bridges	S/SRI/U	
3.	<b>Road Furniture</b>		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained - N.A	Yes/No	
4.	<b>Compliance History</b>		
a)	Status of ATR's & any others - N.A		


Overall Rating : N.A

Satisfactory(S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory(U)	—

Remarks - Road is being constructed under PMGSY-II

NAME: Ex. Radheshyam prajapati

  
 03.12.20  
 J.E  
 R.W.D (W) Division  
 Kishanganj-1

  
 R.E