

FIELD INSPECTION REPORT

Date of Inspection: - 03-12-20	District: - Kishanganj
Division: - Kishanganj-I	Length(km): 2.00
Name of the Road: Laucha TO Bishampur part-II	
Scheme/Programme:	MAINTENANCE
Package No.: - N/A	Road Id No.:
Status of the Project:	Ongoing/Completed /Under Maintenance (Taken under PMGSY-II)
Work is a case of:	New Connectivity/ Up gradation / Maintenance


Sl. No	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction Condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. - N/A	Yes/No
f)	Contraction Joints Provided or not (CC Pavement)	Yes/No
g)	Compaction of flank / slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its Painting - N/A	S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts	S/SRI/U
c)	Condition of railings/Slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained - N/A	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others - N/A	

Overall Rating : - N/A

Satisfactory(S)	-
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory(U)	-

Remarks - Road is taken under PMGSY-II and under Construction.

NAME: Er. Radheshyam prajapati


 03.12.20
 J.E
 R.W.D (W) Division
 Kishanganj-1


 RB