

FIELD INSPECTION REPORT

Date of Inspection: 4/12/2020	District: Kishangari
Division: Kishangari-1	Length(km): 6.100 km
Name of the Road: Gachpara to Nonia Toli	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.: 212-05808068
Status of the Project: Ongoing/Completed /Under Maintenance	(Taken up PMGSY-II)
Work is a case of: New Connectivity/ Up gradation / Maintenance	

S1. No	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction Condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S/U
f)	Contraction Joints Provided or not (CC Pavement)	Yes/No
g)	Compaction of fland / shop & raincuts if any	NA
2.	Cross Drainage	Yes/No
a)	Condition of head walls in Hume pipe culverts including its Painting	S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts	NA
c)	Condition of railings/Slab/approach for Bridges	S/SRI/U
3.	Road Furniture	S/SRI/U
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	NA
4.	Compliance History	
a)	Status of ATR's & any others	- No -

Overall Rating :

Satisfactory(S)	NA
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory(U)	-

(Signature)
4/12/20

AE

NAME: