

## FIELD INSPECTION REPORT

Date of Inspection: 3/12/2020		District: Kishanganj	
Division: Kishanganj-1		Length(km): 25.200 km	
Name of the Road: Kathamatha to Tappu Part I & Part II			
Scheme/Programme: MAINTENANCE			
Package No.:		Road Id No.: 21205808069	
Status of the Project:		Ongoing/Completed /Under Maintenance Taken in PMGSY-II.	
Work is a case of:		New Connectivity/ Up gradation / Maintenance for widening	
S1. No	Parameters to be checked		Remarks
1.	<b>Pavement</b>		S/U
a)	Road Junction Condition	Take up in PMGSY-II for widening. Work in progress under PMGSY-II	S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints Provided or not ( CC Pavement)		Yes/No
g)	Compaction of fland / shop & raincuts if any		Yes/No
2.	<b>Cross Drainage</b>		
a)	Condition of head walls in Hume pipe culverts including its Painting		S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts		S/SRI/U
c)	Condition of railings/Slab/approach for Bridges		S/SRI/U
3.	<b>Road Furniture</b>		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4.	<b>Compliance History</b>		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory(S)	-NA-
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory(U)	-

  
 (Signature) 3/12/20

NAME:

AE