

FIELD INSPECTION REPORT

Date of Inspection :	05/12/2020	District:	Araria
Division :	Forbeggani	Length (km):	2.61 km
Name of the Road:	Kadamaha More to Chakla		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	ongoing
b)	Condition of Surfacing	S/U	ongoing
c)	Riding Quality	S/U	ongoing
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	-
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	-
g)	Compaction of flank/slope & raincuts if any	Yes/No	ongoing
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	-
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	-
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Informatory sign Yes/No to be refined.	board is fixed.
4.	Compliance History		
a)	Status of ATR's & any others	No entry in this agreement	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

(Signature)
05/12/20

NAME:

(Sharmendra Kumar Choudhary)
J.E.