## FIELD INSPECTION REPORT

Date of Inspection : (	3-12 2020	District: SARAN (CHHAPRA)	
Division: SONPUR		Length (km): 3.66	
Name of the Road:	REO RO	AD BHARPURA KHARIKA	
Scheme/Programme:	MAINTENANCE	ON GOING PIN PROGRESS.	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintonance		
		I Granding transportation	

Sl. No.	Parameters to be checked	Remarks	
1.	Pavement	2241	
a)	Road Junction condition		
b)	Condition of Surfacing		
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4	Compliance History		
a)	Status of ATR's & any others		

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	- 100
Unsatisfactory (U)	-

(Signature)

NAME: Rajendra found.

DESIGNATION: A.E