FIELD INSPECTION REPORT

	f Inspection:	04-12.200 1	District: Chopa	01		
Date of		41 5	Length (km): 3.00	km	-1 O	
Name (of the Road:	Sital Dinosa Gram	Re Joi Protesty To	ut St bold	a Tola Roma	
Scheme	e/Programme:	MAINTENANCE				
Package No.:						
Status	of the Project:	Ongoing/Completed/Under Maintenance Not Stored New Connectivity/Up gradation/ Maintenance Not Stored				
Work is a case of: New Connectivity/Op gradati				1001	Remarks	
Sl. No.		Parameters to be checked		Remarks		
1.	Pavement					
a)	Road Junction condition			S/U		
b)	Condition of Surfacing			s/U		
c)	Riding Quality			s/U		
	Road Camber			S/U		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No		
g)	Compaction of flank/slope & raincuts if any			Yes/No		
2.	Cross Drainag	je and some	it and Arithmetic and a second	diffra kinetana		
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U		
c)	Condition of railings/slab/approach for Bridges			S/SRI/U		
3.	Road Furnitur	ė				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No		
4.	Compliance Hi	story	ard p	Marie Care		
a)	Status of ATR's	& any others				

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

Phone 14-12200

(Signature)

NAME:

DESIGNATION: