

FIELD INSPECTION REPORT

Date of Inspection: 5/12/20	District: Lakhimpur
Division: R.D. Camp 2	Length (km): 1.1 km
Name of the Road: Dargah Road to Chh. Bazar	
Scheme/Programme: MAINTENANCE	
Package No.: 01/2019-2021-22	Road Id No:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case off: New Connectivity/Up gradation/ Maintenance	
a) Road Surface condition	S/U
b) Condition of Surfing	S/U
c) Riding Quality	S/U
d) Road Camber	S/U
e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No
f) Construction Joints provided or not (CC Pavement)	Yes/No
g) Compaction of flank slopes & raincuts if any	Yes/No
h) Condition of head walls in Rume pipe culverts including its painting	S/SR/U
i) Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U
j) Condition of railings/slab/approach for Bridges	S/SR/U
k) Whether 1/40 boards/informetry/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
l) Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SR)	
Unsatisfactory (U)	

Work has not started

(Signature) 5/12/20
+E
B. M. P. S.

NAME: .

DESIGNATION: