FIELD INSPECTION REPORT

Date of	Inspection: 0	5-12-2020	District: Saray		
Division	1: RIND (W)	Div Chapra-2	Length (km):		
Name of	f the Road: Is	uwapur to		Agothar	
	/Programme:	MAINTENANCE	Texha of via Navada Cout of Maintenance Road Id No.:	و)	
Package No.:			The state of the s		
	f the Project:		d/Under Maintenance		
	a case of:	The Carrier of the Market Co.	Up gradation/ Maintenance	r Navas salvas salvas, sal	
Sl. No.		Parameters to	be checked	Remarks	
1.	Payement				
a)	Road Junction condition			√S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			√S/U	
d)	Road Camber			/S/U	
e)	Whether free aggregates in c	Yes/No			
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Ycs/No	
4.	Compliance I	listory			
a)	Status of ATR's & any others			No AT	

Overall Rating

Satisfactory (S)	13'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Pogeth Chanter Midbles DESIGNATION: AE