FIELD INSPECTION REPORT

ivision		S-12.2020.	District: SARAN'	- #
lame of	the Road: Ch	Marheura and a to forthi	Length (km): 4, 23	
Scheme/I	Programme:	MAINTENANCE	ikapus Road under 30	DSM (MR)
ackage	No.: Amcalo	NAR/19/0004	Road Id No.: 31306402	010
tatus of	the Project:		/Under Maintenance Combi	
Vork is	a case of:		p gradation/ Maintenance	
Sl. No.		Parameters to	be checked	Remarks
1.	Pavement			
a)	Road Junction condition			√S/U
b)	Condition of Surfacing			vś/U
c)	Riding Quality			√S/U
d)	Road Camber			√S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f) -	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			
2.	Cross Draina	ge		
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
4.	Compliance History			
a)	Status of ATR's & any others			Mo
Overal	Rating :	(0)		101

Overall Rating

Satisfactory (S)	S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Devendrationer NAME: A.E.

(Signature)

DESIGNATION: