

FIELD INSPECTION REPORT

Date of Inspection : 03.12.2020		District: SARAN (CHHAPRA)	
Division : SONPUR		Length (km): 2.850	
Name of the Road: Duothaile Math Se bhaga Baburbani chhitarchak Mandir.			
Scheme/Programme:		MAINTENANCE	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U U
b)	Condition of Surfacing Due to Rain and flood.	S/U U
c)	Riding Quality	S/U S
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NO
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N-R-
g)	Compaction of flank/slope & raincuts if any	Yes/No Y
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U S
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N-R-
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No NO
4.	Compliance History	
a)	Status of ATR's & any others	N.

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	


 (Signature)

NAME: Rajendra Prasad

DESIGNATION: A.E.