FIELD INSPECTION REPORT

Date of Inspec	tion: 05/12/2020	District: Malandy.	
Length (km): A AZA KW;			
Name of the B	ond: Destina k	Indi	
	eme/l'rogramme: MAINTENANCE 3054 FDR		
Package No.: Road Id No.:			
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of: New Connectivity/Up gradation/ Maintenance			La series Tres
Sl. No.	Parau	neters to be checked	Remarks
1. Pav	ement		
a) Ros	Road Junction condition		
b) Co	Condition of Surfacing		S/U
	Riding Quality		S/U
	Road Camber		S/U
e) Wi	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
f) Co	Contraction Joints provided or not (CC Pavement)		Yes/No
g) Co	Compaction of flank/slope & raincuts if any		
2. C	oss Drainage	The second secon	
a) Co	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b) C	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c) C	Condition of railings/slab/approach for Bridges		S/SRI/U
2.37 R	oad Furniture		
a) V	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4 0	Compliance History		
a) S	atus of ATR's & any	others	

Overall Rating

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

Thie Road work is Temporary Restoration work in FDR. Completed.

(Signature) 12/2020

NAME: Mukesh Yadau

DESIGNATION: J. E.