FIELD INSPECTION REPORT

Date of Inspection:	0			
	03-12-20	District: (5)	pagan	
	Go palgan-1	Length (km):	9,71 KM	
Name of the Road:	Sobbala		1.11 . , ,	
Salar 19 Mary 11 Mary				
Deal	MAINTENANCE		•	
Package No.: MR-H	19-20 6/1-1/05	Road Id No.:		
Status of the Project:	Ongoing/Completed/Under Maintenance			- ///// >
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓			
CONTRACTOR OF THE PROPERTY OF THE PARTY OF T				

WOLK IS	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Payement		
a)	Road Junction condition	8/u (S)	
Ġ)	Condition of Surfacing	s/u (S)	
c)	Riding Quality	s/u (2)	
d)	Road Camber .	s/u (S)	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No MA	
g)	Compaction of flank/slope & raincuts if any	Yes/No Satisfa	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	s/sri/u (\$)	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No les	
4.	Compliance History		
a)	Status of ATR's & any others	NO ATR	

Overall Rating

Satisfactory (S)	(2)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

AME: Ajoy kumorti 112/20 4/12/202

reutive francison

(Signature)