

FIELD INSPECTION REPORT

Date of Inspection : 5/12/20	District: Musaffapur
Division : Musaffapur east	Length (km): 3.85 km
Name of the Road: Baimya Mohanp. NH to Pasa Village Road	
Scheme/Programme:	MAINTENANCE New maintenance policy
Package No.:	Road Id No.:
Status of the Project:	<input checked="" type="checkbox"/> Ongoing/Completed/Under Maintenance
Work is a case of:	<input checked="" type="checkbox"/> New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	N/A S/U
b)	Condition of Surfacing	N/A S/U
c)	Riding Quality	N/A S/U
d)	Road Camber	N/A S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No N/A
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No Board fixed
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

work Not started

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)
5/12/20

NAME: Baidyanath chandhary

DESIGNATION: JE, Mahapur-1.