

Latitude: 26.157201
 Longitude: 85.099315
 Elevation: 74.82m
 Accuracy: 8.0m
 Time: 05-12-2020 15:56

FIELD INSPECTION REPORT

Date of Inspection:	5-12-2020	District:	Muzaffarpur
Division:	R.W.D. Muz. West	Length (km):	4.20 km / 2.6 km
Name of the Road:	Basithur p.w.D Road to Gangwathi		
Scheme/Programme:	MAINTENANCE		
Package No.:	1 RH - MU / Hry / 19/2014	Road Id No.:	31507202071
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

1-18-107

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	2 S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

5/12/2020
 (Signature)

NAME: R.K. Gohary

DESIGNATION: A.E