## FIELD INSPECTION REPORT

Date	of Inspection:	03-12-20	District: Hugati		
Divis	ion : Out b M	uz.west	Length (km): 190k		
Name	e of the Road: D	pictantia PND R	and to Hanuman Mandir		
Scher	ne/Programme:	MAINTENANCE			
	age No.:	LOuvalna/Completed	Road Id No.1		
Status of the Project: Work is a case of:		Ongoing/Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance			
*****	THE REAL PROPERTY AND ADDRESS OF THE PERSON NAMED IN COLUMN TWO PERSONS ASSESSED.	The same in the sa	The state of the section of the sect	Remarks	
SI. No	).	Parameters to	Parameters to be checked		
1.	Pavement				
a)	Road Junction condition			, SrU	
b)	Condition of Surfacing			∪s/U	
c)	Riding Quality			SIU	
d)	Road Camber			SIU	
e)	Whether free from defects such as visible cracks, exposed yes/No aggregates in case of CC Pavement: C.c. Ho Province				
f)	Contraction Joints provided or not (CC Pavement) No Provise Yes/No			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			&/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			-8/SRI/U	
c)	Condition of railings/slab/approach for Bridges			"S/SRI/U	
3.	Road Furniture				
1)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
	Compliance History				
)	Status of ATR's & any others			19-0	

Overall Rating

Satisfactory (S)	191
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature) 3-6

NAME:

**DESIGNATION:**